

VISUAL INSPECTION REPORT CLIENT # 2413

901 N. Penn Street, Regatta Building Philadelphia, PA. 19123 215-791-8400

Date and Time of Visual Inspection:	3/23, 2024 @ 10 AM
Lead Dust Sampling	JERRY EHRLICH, Tech# D-I-18846-23-00082
Technician: Client Name:	Jane Doe
Cell / Email:	21 5 555 1212 / NoEmail@Gmail.com
Property Address: Number of Bedrooms:	40271 Main Street Unit 1 Phila Pa 19123 1

The purpose of the visual inspection is to identify visible areas of dust, paint chips, painted debris, and deteriorated paint. (Note location: walls, ceiling, floors, doors, windows, trim, cabinets, etc.).

Room/Location:	Deteriorated Paint	Debris	Visible Dust	Notes:
NONE	NO	NO	NO	NONE
	SAMPLE			

<u>Tenant Notes</u>: Tenant was home and let me into the 1st floor unit to inspect. The Unit was clean and uncluttered. No Children are present at location.

Additional Notes: Must use RRP (Renovate, Repair and Paint) contractor that uses Lead Safe Work Practices.

<u>Property Description & Layout:</u> Circa 1925 2 story Townhouse with Apt Unit on 1st Floor and 2nd Floor. I tested the 1st Floor only. Living room is upfront with Kitchen in the middle and the bedroom in the back.

EXTERIOR FACADE OF SUBJECT PROPERTY: (40271 Main Street UNIT 1 Phila Pa 19123)



The following pages contain the corresponding photos of the items to be repaired / painted.

All items are to be Repaired / Painted using "Lead Safe" work practices with an RRP Certified Contractor.

SEE ATTACHMENT IN EMAIL



to learn about "Lead Safe" work practices.

PICTURES of items to be fixed.

(NONE)

The following pages depict where each of the dust wipe samples were collected.

(As indicated by the RED X)

Living Room – ONLY Window & CENTER Floor

One dust wipe sample was collected from this Wooden windowsill and one dust wipe sample was collected from the Laminate floor area directly below this windowsill.

(As indicated by the RED X)



Back Bedroom – ONLY Window & CENTER Floor

One dust wipe sample was collected from this Wooden windowsill and one dust wipe sample was collected from the Laminate floor area directly below this windowsill.

(As indicated by the RED X)



This page is a copy of the "CHAIN OF CUSTODY" form that is used to record and track the dust wipe samples sent to the laboratory for analysis & results.

Chain o		of Custody SUBM		SUBMITTING COMPANY		CONTACT INFORMATION								
				Lead Safe Resources LLC			JERRY EHRLICH							
1 A					901 N P	enn St Re	gatta Bldg	Office:	215-7	91-81	00			
					Philac	lelphia, P	A. 19123	Cell:	610-4	96-03	69			
75 79	1 8 AUC													
EPA Certified P	aint Inspection				Client #	2	413	Email:	LeadSaf	eReso	urces	@gma	ail.com	
PROJECT NUMBER	2413	SAMPLING DATE:	3/23/2024		REQUESTE	O ANALYSIS	LEAD	Request	Turnaroun	d time (please	check	(one)	
PROJECT ADDRESS	40271 Ma	in Street Unit 1 Philo	delphia PA	19123	SINGLE	WIPE DUST	X	SAME DAY	()	2	4 Hour	()	
SAMPLE START TIME	10:00AM	SAMPLE END TIME	10:21AM		сом	POSITE SOIL	()	48 Hour	()	72 I	nours	(X)	
TECHNICIAN	JER	RY EHRLICH			PAINT CHIP	% By Wt.	mg/cm ²	If none indicated, default is 72 h			72 hou	ırs.		
LABID	CLIENT SAMPLE ID	DESCRIPTIO	DN	ws,	WT, F	WIPE AREA (e.g. 12in X 12in	CLIENT COMMENTS						
	1	Living Room - ONLY	Window	WINDO	W SILL		X 10"	Risk Assessor: Anthony Galasso						
	2	Living Room - CENTI	ER Floor	FLO	OOR		12" x 12"	Samples	Shipped	Ţ.,	5			
	3	Back Bedroom - ON	LY Window	WINDO	W SILL	2"	X 10"							
	4	Back Bedroom - CE	NTER Floor	FLO	OOR		12" x 12"							
	5	Control Sample -	BLANK	BL	ANK	ВІ	LANK	SAMPLE CONDITION						
								SEALS INTAC	CT	Y	N			
								CONTAINER	S LABELED	Y	N			
								RECVD & A	CCEPTED	Y	N			
								LAB REMAR	KS					
								LAB						
								PROJECT NUMBER						
SAMPLE	S RELINQUISI	HED BY		SAM	PLES RECEIV	ED BY			Date	e 1	IME			
Lead Safe Resou	Lead Safe Resources, LLC - Jerry Ehrlich							3/23/	/2024		AM	1:0	10 PM	
Certificate Nu	mber D-I-1	8846-23-00082									AM		PM	
Signature: 🏻 🚓	ry <u>F</u> hrlich										AM		PM	

LAB REPORT



30105 Beverly Road Romulus, MI 48174 Ph: 734-629-8161

Certificate of Analysis: Lead In Dust Wipe by EPA Method 7000B/NIOSH 7082*

Lead Safe Resources LLC 901 N PENN STREET REGATTA BLVD Philadelphia, PA 19123

Attn: Anthony Gale Phone: 215 791 8400 Anthony Galasso

Client Project: 2413

Project Location: 40271 Main Street Unit 1 Phila Pa 19123

Sampling Date : 03/23/2024
Date Received : 03/25/2024
Date Analyzed : 03/26/2024
Date Reported : 03/26/2024

Lab Sample ID	Client Code	Sample Description	Length (inch)	Width (inch)	Area (Sq ft)	Results Lead µg/ft2 *
9400629	1	LIV RM RT WIN WS	2	10	0.14	<36.0
9400630	2	LIV RM CT FL F	12	12	1.00	<5.00
9400631	3	BDRM RT WIN WS	2	10	0.14	<36.0
9400632	4	BDRM CT FL F	12	12	1.00	<5.00
9400633	5	CONTROL SAMPLE BLANK	N/A	N/A	N/A	N/D

Analyst Signature





Email: leadsaferesources@gmail.com



CERTIFICATE

FOR ADMIN USE ONLY: ling listed below, and vith EPA regulations, valid for 4 years from

Lip

00082
Firm Certification # Philadelphia Department of Public Health Certification of Lead SAFE Status ne welling listed below, and lance with EPA regulations, licate is valid for 4 years from con rm that I By signing this certificat ection dust e samples ected in c ust wip state that it does not hav iorated nd that lead cont ated di lead star were tested, and did not date of validation. 40271 Main Street **1**# or Floor

Phila., PA 191 **23** D-I-18846-23-00082 Lead Safe Resources, LLC. Certifying Company (print) Risk Assessor, Lead Inspector PA Lic. # or EPA Firm Certification # 3/25/2024 ian Name (Signature) Date of Verification Pursuant to Philadelphia Code Title 6, Chapter 6-800, SS 6-803 (3)(c) the Landlord/Agent of the above property must give a copy of this certificate to the Tenant/Lessee and send a copy of the certificate, along with a copy of the dust wipe samples test results for this dwelling to the Department of Public Health, Lead, LEAD SAFE Health scan it and submit it to https://www.tifica. If you have questions call 215-685-2718 or e-mail CERTIFICATION, G/O Department of Public phil gov/lo cert hila.ge

END OF REPORT
THANK YOU FOR YOUR BUSINESS!